
The Six Sigma Practitioner's Guide to Data Analysis

Second Edition

Donald J. Wheeler

Fellow of the American Statistical Association

Fellow of the American Society for Quality



SPC Press

Knoxville, Tennessee

Contents

About the Author	<i>xi</i>
Acknowledgments	<i>xii</i>
Preface to the Second Edition	<i>xii</i>
Introduction	<i>xiii</i>
PART ONE: THE FOUNDATIONS OF DATA ANALYSIS	1
One Four Statistical Problems	3
1.1 Descriptive Statistics	3
1.2 Probability Theory	5
1.3 Statistical Inference	6
1.4 The Homogeneity Question	8
1.5 Two Perspectives on These Problems	9
1.6 Axioms of Data Analysis	12
1.7 Observational Studies and Experimental Studies	16
1.8 Summary	17
Two Descriptive Statistics and Homogeneity	19
2.1 What Does the Standard Deviation Statistic Do?	19
2.2 What Descriptive Statistics Do Not Do	29
2.3 Local Measures of Dispersion	30
2.4 Are the Data Homogeneous?	33
2.5 The Difference between Global and Local	38
Three Process Behavior Charts	41
3.1 The Chart for Individual Values	41
3.2 What Do We Gain from the mR Chart?	44
3.3 What Makes the XmR Chart Work?	46
3.4 How Many Values Do I Need for Limits?	50
3.5 Rules for Detecting Nonhomogeneity	53
3.6 Average and Range Charts	58
3.7 Chunky Data	62
3.8 Caution regarding Software	65
3.9 Where Do We Go from Here?	66

Four	Statistics, Parameters, and Inference	67
4.1	The Concept of a Probability Model	67
4.2	Some Cautions regarding Probability Models	71
4.3	Elements of Statistical Inference	72
4.4	Interval Estimates of Location	76
4.5	Interval Estimates of Dispersion	84
4.6	Practical Statistical Inference	86
4.7	Interpreting “Degrees of Freedom”	88
4.8	Summary	91
PART TWO: THE TECHNIQUES OF DATA ANALYSIS		93
Five	Data Collected under One Condition	95
5.1	What Can We Say about Our Process?	95
5.2	But What about the Significance Levels?	99
5.3	Bead Board No. 3	100
5.4	The Data for NB10	105
5.5	Summary	107
Six	Data Collected under Two Conditions	111
6.1	Detecting a Difference with Histograms	111
6.2	Detecting a Difference with <i>XmR</i> Charts	113
6.3	Using an Average and Range Chart	116
6.4	The Analysis of Means	119
6.5	The Two-Sample Student’s <i>t</i> -Test	122
6.6	The Paired <i>t</i> -Test	125
6.7	NB10 Revisited	128
6.8	Summary of Comparing Two Conditions	130
Seven	Data Collected under Three or More Conditions	133
7.1	<i>XmR</i> Charts for Each Treatment	133
7.2	Average and Range Charts	135
7.3	Analysis of Means	136
7.4	Analysis of Variance	137
7.5	The Tukey Post-Hoc Test	145
7.6	NB10 Again	146
7.7	Summary of Comparing Several Conditions	148

Eight	Data Collected at Three or More Values for X	151
	8.1 The Universe Had a Definite Beginning	151
	8.2 Evaluating Terms in the Model	154
	8.3 Regression: One Line or Two?	156
	8.4 A Deterministic Relation with Controlled X Values	158
	8.5 A Deterministic Relation with Uncertain X Values	160
	8.6 X and Y Are Random Variables	162
	8.7 Data Snooping	166
	8.8 Trends	170
	8.9 The Role of the Scatterplot	170
	8.10 The Problem of Regression Models	171
Nine	Count-Based Data	175
	9.1 Two Types of Counts	175
	9.2 Interval Estimates for Universe Proportions	177
	9.3 Homogeneity for Counts	180
	9.4 Should I Compare Counts or Rates?	182
	9.5 A Caution regarding Counts on an XmR Chart	183
	9.6 Outliers or Signals?	186
	9.7 Comparing Two Proportions with Charts	187
	9.8 Comparing Two Single Proportions	189
	9.9 Comparing Proportions for Several Conditions	192
	9.10 Summary	196
Ten	Counts of Events	197
	10.1 Inference for Counts of Events: One Condition	197
	10.2 Using the Poisson Model	201
	10.3 Comparing Two Conditions	202
	10.4 Comparing Several Conditions	205
	10.5 Summary	206
Eleven	Counts for Three or More Categories	207
	11.1 Categorical Frequencies for One Condition	207
	11.2 Categorical Data for Two or More Conditions	215
	11.3 Summary	218

PART THREE: THE KEYS TO EFFECTIVE DATA ANALYSIS	219
Twelve	The Dual Nature of Trouble 221
12.1	“We Are in Trouble” 221
12.2	A New Definition of Trouble 223
12.3	The Four Possibilities for Any Process 225
12.4	Research and Experimentation Are Not Enough 235
12.5	Operating a Process Predictably 241
12.6	Summary 242
Thirteen	Capability and Performance Indexes 243
13.1	The Voice(s) of the Process 243
13.2	The Voice of the Customer 245
13.3	The Capability Ratio, C_p 248
13.4	The Centered Capability Ratio, C_{pk} 250
13.5	The Performance Ratio, P_p 253
13.6	The Centered Performance Ratio, P_{pk} 256
13.7	Using the Four Ratios Together 257
13.8	The Ratios and the Four Possibilities 259
13.9	Operational Improvement 260
13.10	Short-Term and Long-Term Capability 262
13.11	Interval Estimates for Capability Indexes 262
13.12	Summary 267
Fourteen	Using the Effective Cost of Production and Use 269
14.1	The Effective Cost of Production and Use 269
14.2	The Baseline Cost of Production and Use 271
14.3	The Centered Cost of Production and Use 272
14.4	The Predictable Cost of Production and Use 273
14.5	The Minimum Cost of Production and Use 275
14.6	Using the Effective Cost of Production and Use 276
14.7	Summary 280
Fifteen	The Basis for the Effective Cost of Production and Use 281
15.1	The Structure of the <i>Effective Cost of Production and Use</i> 281
15.2	The Average Excess Costs 282
15.3	Finding the <i>Effective Cost of Production and Use</i> 288
15.4	Summary of <i>ECP&U</i> for Measurements 289
15.5	The Effective Cost of Production for Counts of Items 290
15.6	The Effective Cost of Production for Counts of Events 291

Sixteen	The Six Sigma Zone	293
	16.1 The <i>Effective Cost of Production and Use</i> Curves	293
	16.2 An Illustration	299
	16.3 The Six Sigma Zone	301
	16.4 Summary	302
Seventeen	Some Problems	305
	17.1 Problems with Defects per Million	305
	17.2 Problems with Defects per Million Opportunities	310
	17.3 Problems with FMEA Risk Priority Numbers	311
	17.4 Problems with Special Causes	316
	17.5 Problems with DMAIC Models	318
	17.6 Do We Need a Gauge R&R Study?	321
	17.7 Problems with Narrowly Defined Projects	323
	17.8 Summary	331
Eighteen	Two Models for Process Improvement	333
	18.1 Getting Started	333
	18.2 Characterize the Status of the Process Outcomes	334
	18.3 Outcomes in the State or Brink of Chaos	335
	18.4 Outcomes in the Threshold State	337
	18.5 Outcomes in the Ideal State	338
	18.6 Focusing Improvement on Strategic Objectives	338
	18.7 Summary	341
Nineteen	An Honest Gauge R&R Study	343
	19.1 The AIAG Gauge R&R Study	343
	19.2 The “Percentages” of the Total Variation	346
	19.3 The “Percentages” of the Specified Tolerance	350
	19.4 The “Number of Distinct Categories”	353
	19.5 The AIAG Guidelines	353
	19.6 What Can You Learn from the AIAG Study?	357
	19.7 An Honest Gauge R&R Study	358
	19.8 Summary	363

Appendix		367
Table A.1	Bias Correction Factors for Measures of Dispersion	368-369
Table A.2	XmR Charts: Charts for Individual Values	370-371
Table A.3	Average and Range Charts Based on the Average Range	372-373
Table A.4	Average and Range Charts Based on the Median Range	374-375
Table A.5	Average and Standard Deviation Charts Based on the Average Standard Deviation Statistic	376-377
Table A.6	Average and Standard Deviation Charts Based on the Median Standard Deviation Statistic	378-379
Table A.7	Critical Values for Student's t Distributions	380-381
Table A.8	Percentiles of Chi-Square Distributions	382-383
Table A.9	Overall Alpha-Levels for Average Charts	384
Table A.10	Overall Alpha-Levels for Range Charts	385
Table A.11	Quick Scale Factors for Range-Based ANOM	386-388
Table A.12	Quick Scale Factors for Pooled Variance ANOM	389-391
Table A.13	Percentiles of the F-Distribution	392-397
Table A.14	Percentiles of the Studentized Range Distribution, q	398-403
Table A.15	Factors for 90% Interval Estimates of C_p and P_p	404
Table A.16	Factors for 90% Interval Estimates of C_{pk} and P_{pk}	405
Table A.17	The <i>Effective Cost of Production and Use</i> When All Nonconforming Units Are Scrapped	406-408
Table A.18	The <i>Effective Cost of Production and Use</i> When All Nonconforming Units Are Reworked	409-411
Table A.19	The <i>Effective Cost of Production and Use</i> When the Cost of Rework Is Half of the Cost of Scrap and the Average Is on the SCRAP Side of the Target	412-414
Table A.20	The <i>Effective Cost of Production and Use</i> When the Cost of Rework Is Half of the Cost of Scrap and the Average Is on the REWORK Side of the Target	415-417
Index		419