
*TWENTY THINGS
YOU NEED
TO KNOW*

Donald J. Wheeler, Ph.D.
Fellow of the American Statistical Association
Fellow of the American Society for Quality



SPC Press

CONTENTS

About the Author	<i>vi</i>
Preface	<i>vii</i>
1. The Two Mistakes of Data Analysis	1
2. Two Types of Data	5
3. The Origin and Structure of Variation	9
4. Three Questions for Success	19
5. Where Do the Scaling Factors Come From?	23
6. Why Not Just Use the Standard Deviation Statistic?	27
7. Don't We Need Normal Data?	33
8. But the Software Transforms the Data!	37
9. Why Use Three-Sigma Limits?	43
10. How Many Data Do I Need for Limits?	47
11. When Do I Need to Revise the Limits?	55
12. But the Limits Are Too Wide!	63
13. When Do We Use a Median Moving Range?	77
14. What Can Be Considered a Signal?	81
15. Why a Process Behavior Chart Is the First Step in Data Analysis	91
16. When Do We Use Subgrouped Data?	101
17. What About p -Charts?	109
18. Don't We Need to Remove the Outliers?	117
19. Don't We Need Good Measurements?	123
20. The Axioms of Data Analysis	131
For Further Reading	137
Tables for Charts for Subgrouped Data	141
Index	147

*There is light enough
for those who wish to see,
and darkness enough
for those who are otherwise inclined.*

Blaise Pascal

*In this world
two plus two
is only equal to four
on the average.*

David S. Chambers